

2.0 INSTALLATION / SET UP

NOTE: TO PREVENT AMPLIFIER DAMAGE, THE TRANSDUCER MUST BE CONNECTED BEFORE APPLYING POWER TO THE AMPLIFIER.

2.1 Wiring

The Universal In-Line Amplifier can be powered from a 18 to 32 volt single voltage supply. The following diagrams show the wiring to the supply and readout.

Cables should be stripped back 3 inches with the wires stripped and tinned 1/2 inch. Connections to the terminal block are made by pressing the orange levers and inserting the wires into the hole next to the levers. The terminal block will accept wire up to AWG 20.

Install a shunt cal resistor with the value specified on the transducer data sheet.





Figure 2-1. Transducer to In-line Wiring



NOTE: Do not connect anything to pin 2.

Figure 2-1. DCM 492 Universal In-Line Wiring

NOTE: TO PREVENT AMPLIFIER DAMAGE, THE TRANSDUCER MUST BE CONNECTED BEFORE APPLYING POWER TO THE AMPLIFIER.

2.2 Setup

Use the following procedure for setting up the excitation and the coarse gain:

1. Determine the EXCITATION VOLTAGE required by the transducer being used.
2. Set the EXCITATION SELECT JUMPER as shown below: (See Fig. 1-1 for location of jumpers).

	DO NOT USE
	5V
	2.5V

3. Determine the sensitivity of the transducer in mV/V from the transducer calibration sheet.
4. Set the COARSE GAIN SWITCH (See Fig. 1-1 for location of switch) to the nearest mV/V setting in the corresponding excitation column in Table 1.

Table 1: Coarse Gain Setup

SWITCH POSITIONS FOR GIVEN SENSITIVITY AND CHOSEN EXCITATION		Selected Bridge Excitation	
		2.5 V	5 V
	1 mV/V	1 mV/V	0.5 mV/V
	1.5 mV/V	1.5 mV/V	0.75 mV/V
	2.4 mV/V	2.4 mV/V	1.2 mV/V
	3 mV/V	3 mV/V	1.5 mV/V
	2 mV/V	2 mV/V	1 mV/V
	5 mV/V	5 mV/V	2.5 mV/V
	2.4 mV/V	2.4 mV/V	1.2 mV/V
	7 mV/V	7 mV/V	3.5 mV/V
	4 mV/V	4 mV/V	2 mV/V
	9 mV/V	9 mV/V	4.5 mV/V
	5 mV/V	5 mV/V	2.5 mV/V
	6 mV/V	6 mV/V	3 mV/V
	7 mV/V	7 mV/V	3.5 mV/V
	8 mV/V	8 mV/V	4 mV/V

Normal Transducer Sensitivity

2.3 Panel Mounting Template

The Universal In-line Amplifier can be easily mounted to a panel by using the template below for marking the holes in the panel. The cover must be removed to get access to the mounting holes. Use #6 or #8 screws for mounting box to panel.

CENTER HOLE LOCATION FOR PANEL




Figure 2-3. Panel Mounting Template

3.0 CALIBRATION

3.1 Calibration

- Step 1. Apply power and allow unit to stabilize for 10 minutes.
- Step 2. With zero load or pressure on the transducer adjust the ZERO potentiometers to indicate zero on the readout instrument connected to the output.
- Step 3. Apply full scale pressure or load to the transducer and adjust the SPAN potentiometer to indicate full scale on the readout instrument.
- Step 4. Re-check zero and full scale (repeat steps 2 & 3)

3.2 Using Shunt Calibration

Cooper transducers feature a calibration technique called shunt calibration. This method applies a known resistance across one leg of the transducer, which simulates an output, as if a load or pressure was applied to the transducer. When performing shunt calibration the transducer should be at ZERO pressure or load. The full scale output and shunt cal output is found on the TRANSDUCER CALIBRATION SHEET. This information can be used to calibrate the amplifier's output current and the readout's display with the following equations.

Transducer Calibration Data

Full Scale Output = _____ mV/V

Shunt Resistor Value of _____ Ohms

Shunt Cal Output = _____ mV/V

The following equations are used to calculate output current and display units:

Formula To Calculate Output Current

$$\left(\frac{\text{SHUNT CAL OUTPUT}}{\text{FULL SCALE OUTPUT}} \times 16\text{mA} \right) + 4 \text{ mA} = \text{OUTPUT CURRENT}$$

$$\left(\text{_____} \times 16\text{Ma} \right) + 4\text{mA} = \text{_____}$$

Formula To Calculate Display Units

$$\frac{\text{SHUNT CAL OUTPUT}}{\text{FULL SCALE OUTPUT}} \times \text{FULL SCALE UNITS} = \text{DISPLAY UNITS}$$

$$\text{_____} \times \text{_____} = \text{_____}$$

- Step 1. Apply power and allow the amplifier to warm up
- Step 2. With zero load or pressure on the transducer adjust the ZERO potentiometer to indicate zero on the readout instrument.
- Step 3. Connect a jumper across PINS 5 & 6 of the power terminals (See Fig. 1-1) or wire in a switch as shown in wiring section. Adjust the SPAN potentiometer to the calculated current or calculated units on the readout instrument.
- Step 4. Disconnect the shunt cal jumper or release the shunt cal switch and repeat steps 2 & 3 if needed.

4.0 WARRANTY REPAIR POLICY

Limited Warranty On Products

Any Cooper Instruments product which, under normal operating conditions, proves defective in material or in workmanship within one year of the date of shipment by Cooper will be repaired or replaced free of charge provided that a return material authorization is obtained from Cooper and the defective product is sent, transportation charges prepaid, with notice of the defect, and it is established that the product has been properly installed, maintained, and operated within the limits of rated and normal usage. Replacement or repaired product will be shipped F.O.B. from our plant. The terms of this warranty do not extend to any product or part thereof which, under normal usage, has an inherently shorter useful life than one year. The replacement warranty detailed here is the buyer's exclusive remedy, and will satisfy all obligations of Cooper whether based on contract, negligence, or otherwise. Cooper is not responsible for any incidental or consequential loss or damage which might result from a failure of any and all other warranties, express or implied, including implied warranty of merchantability or fitness for particular purpose. Any unauthorized disassembly or attempt to repair voids this warranty.

Obtaining Service Under Warranty

Advance authorization is *required* prior to the return to Cooper Instruments. Before returning the item, contact the Repair Department c/o Cooper Instruments at (540) 349-4746 for a Return Material Authorization number. Shipment to Cooper shall be at buyer's expense and repaired or replacement items will be shipped F.O.B. from our plant in Warrenton, Virginia. Non-verified problems or defects may be subject to a \$100 evaluation charge. Please return the original calibration data with the unit.

Repair Warranty

All repairs of Cooper products are warranted for a period of 90 days from date of shipment. This warranty applies only to those items that were found defective and repaired; it does not apply to products in which no defect was found and returned as is or merely recalibrated. It may be possible for out-of-warranty products to be returned to the exact original specifications or dimensions.

Technical description of the defect: In order to properly repair a product, it is *absolutely necessary* for Cooper to receive information specifying the reason the product is being returned. Specific test data, written observations on the failure and the specific corrective action you require are needed.